

Importer's name	Finder plc
Importer's address	Opal Way Stone Business Park Stone Staffordshire ST15 0SS UK

Declares under sole responsibility that the product as originally delivered:

Product	92 Series: Sockets for 62 Series Relays
Manufacturer's name	Finder SpA
Manufacturer's address	Via Drubiaglio 14 10040 Almese (TO) Italy

Complies with the following statutory requirements and carries the UKCA mark accordingly	By conforming to the following designated standards.
Electrical Equipment (Safety) Regulations 2016 No.1101 [as amended]	BS EN 60664-1:2007
Restriction of the Use of Certain Hazardous Substances in Electrical and Electronic Equipment Regulations 2012 No.3032 [as amended]	BS EN IEC 63000:2018

Signed for and on behalf of:	Finder plc
Issued at:	Stone, Staffordshire
Date:	21 st June 2021
Name:	Jonathan Stanford
Function:	Managing Director
Signature:	