

Type: **+IZM-XHIB**
Article No.: **225680**

Ordering information

Description			1 make contact
-------------	--	--	----------------

Notes concerning the product group

Availability is also signalled locally by the OK indication and means:

- Mechanical reclosing lockout reset (red reset pin)
- Spring energy store tensioned
- Undervoltage release excited
- Shunt release not excited
- Electrical interlock in the plant control cancelled
- Mechanical interlock ineffective
- Locking devices not activated

The standard terminals are screw-type; spring-loaded terminals are optional.

Moeller GmbH, Hein-Moeller-Str. 7-11, D-53115 Bonn
E-Mail: catalog@moeller.net, Internet: www.moeller.net, <http://catalog.moeller.net>
Copyright 2006 by Moeller GmbH. Subject to modifications. HPL-C2006GB-INT V2.3